

November 30, 2000

00V-403

Dear Honda Dealer:

RE: 2000/2001 CBR929RR/RE - SAFETY RECALL NOTICE

VIN Range:

2000 Model Year -- ALL

2001 Model Year

RR, 49 state version: JH2SC440\*1M100001 to JH2SC440\*1M103117

RE, 49 state version: JH2SC443\*1M100001 to JH2SC443\*1M101150

RR, CALIF. version: JH2SC441\*1M100001 to JH2SC441\*1M100434

RE, CALIF. version: JH2SC444\*1M100001 to JH2SC444\*1M100126

EFFECTIVE IMMEDIATELY, YOU MUST NOT SELL ANY NEW OR USED 2000/2001 CBR929RR/RE IN YOUR INVENTORY. This is due to an important SAFETY RECALL that American Honda is conducting. These units are subject to a potential safety-related problem with the outer clutch basket.

We will provide floorplan interest assistance for units in your inventory during this correction period. Details will follow shortly. You will also receive details concerning future product shipments at a later date.

If you have recently sold a 2000/2001 CBR929RR/RE, please immediately submit the warranty registration information via HONDANET for Windows.

A Service Bulletin with complete RECALL information will be mailed to you soon.

Thank you for your cooperation.

Sincerely,

AMERICAN HONDA MOTOR CO., INC.

Robert E. Clever  
Senior Manager - Service  
Bulletin Number: 00-